



VEH Photo #43 - Right Side Tag-Axle Spindle With Torn and Distorted Bearing Cage